

Coast Guard Vessel Critical Profile of Taki-Tooo

Four (4) pages total including this cover

Vessel Critical Profile

Name/ TAKI-TOOO

Primary VIN/ 579874

Call/ WYJ8274

Flag/ US

Alt VIN's

Type

579874

Official Number

35-707

Hull Number

---Involved Parties---

Role	Name	Party Id
Flag State	UNITED STATES	833031
Managing Owner	DAVIS FISHERIES INC	174889
Owner	DAVIS FISHERIES INC	174889
Operator	GARIBALDI CHARTERS	171202
Managing Owner (Trustee)	DAVIS FISHERIES INC	174889

---Vessel Specifics---

Service/ Passenger (More Than 6)	Gross Tons(GT ITC)/	Hailing Port/ GRESHAM OR,
Propulsion/ Diesel Reduction	Gross Tons(GRT)/ 14	Date Keel Laid/ 01Jan1977
Route/ OO: Oceans	Deadweight Ton/	Date Delivered/ 01Jan1977
Ahead HorsePower/ 250	Length/ 32.5 (ITC)/	Hull Material/ FRP
Astern HorsePower/ 250	Super Structure Color/ White	Hull Color/ Red
Class/ Passenger Ship	Type/ General	SubType/

---VDS Documents---

Document	Activity #	Agency	Port	Issued	Expires	Status
CERTIFICATE OF DOCUMENTATION		USCG	PORVD	26Sep2002	31Oct2003	VALID

---Certificate/Document Status---

Document	Activity #	Agency	Port	Issued	Expires	Status
SAFETY RADIO		FCC	NONCG	10Apr2001	10Apr2006	VALID
TELEPHONE Certificate of Inspection - Amended Stability Letter	1742449	USCG	PORMS	13Mar2001	13Mar2006	Issued/Effective
			PORMS	24Apr1990		

---Hull and Re-inspections---

Re-Inspection Due Date/ 13Mar2004
 Internal Structural Next Due Date/
 DryDock Next Due Date/ 29Nov2003
 Wood Keel Bolt Next Due Date/

Inspection Type/ Annual Inspection

---All Open Activities---

Total Open Activities/ 1

1. Activity #/ 1763828 Orig Port/ PORMS Owner Port/ PORMS Start Dt/ 26Mar2003
 Role Type/ Subject to Marine Inspection Activity Type/ Vessel Inspection
 Activity Subtypes/ DAMAGE SURVEY and REPAIRS
 Status/ Open - In Progress Date Status Last Changed/ 26Mar2003
 Notes (Truncated)/ Damage survey March 26, 2003 TAKI-TOOO, O.N. 579874 Attended subject vessel 26Mar03 to assess damage sustained from a fire. Met with owner Mick Buell. The fire started at the shore tie connection starboard side bulkhead ivo entry door to cabin. Unable to ascertain exact cause as the shore tie connection had been taken by the insurance surveyor. Owner claims the connection was a standard m

---All Closed Activities (W/in 18 months)---

Total Closed Activities/ 8

1. Activity #/ 1767477 Orig Port/ PORMS Owner Port/ PORMS Start Dt/ 22Apr2003
 Role Type/ Subject to Marine Inspection Activity Type/ Vessel Inspection
 Activity Subtypes/ DEFICIENCY CK and REPAIRS
 Status/ Closed - Agency Action Complete Date Status Last Changed/ 01May2003
 Notes (Truncated)/ 22APR03: Attended vessel moored at the port of Garibaldi, OR to inspect repairs made to vessel (post-fire) as well as to clear outstanding CG-835 items issued earlier this year. Vessel rep was Mr. Mick Buell (master/owner). Found all repairs called out by worklist items HO01 thru HO09, issued during the damage survey conducted on 01APR03, were completed and were all sat. Also, inspected those
2. Activity #/ 1742449 Orig Port/ PORMS Owner Port/ PORMS Start Dt/ 13Mar2003
 Role Type/ Subject to Marine Inspection Activity Type/ Vessel Inspection
 Activity Subtypes/ ANNUAL
 Status/ Closed - Agency Action Complete Date Status Last Changed/ 21Mar2003
 Notes (Truncated)/ Conducted annual inspection, issued 8 CG-835's, cleared none and 8 remain outstanding. Attended vessel moored in Garibaldi, Oregon, to conduct annual inspection. Met with vessel operator Mr. Mitch Buel to discuss the scope of the inspection. Conducted the inspection in accordance with unit's checklist. All satisfactory with the exception of the items listed in the deficiency summary. Explain
3. Activity #/ 1614429 Orig Port/ PORMS Owner Port/ PORMS Start Dt/ 08May2002
 Role Type/ Subject to Marine Inspection Activity Type/ Vessel Inspection
 Activity Subtypes/
 Status/ Closed - Agency Action Complete Date Status Last Changed/ 21May2002
 Notes (Truncated)/ CHANGED OPERATORS NAME AND ADDRESS AS PER LETTER FROM DAVIS FISHERIES DATED 4 MAY 2002. BARBARA VONPEGERT
4. Activity #/ 1486569 Orig Port/ PORMS Owner Port/ PORMS Start Dt/ 20Mar2002
 Role Type/ Subject to Marine Inspection Activity Type/ Vessel Inspection
 Activity Subtypes/ ANNUAL
 Status/ Closed - Agency Action Complete Date Status Last Changed/ 09May2002

Notes (Truncated)/ Completed first annual reinspection. Cleared PORMS item 1 of 29NOV01. Issued eleven requirements. No other requirements are outstanding from previous inspections. Visited vessel afloat at Garibaldi Marina to complete annual reinspection. Inspected vessel in accordance with local check sheet finding eleven "prior to sail" requirements. Vessel clearly not ready for inspection and operator do

5. Activity #/ 1393827 Orig Port/ PORMS Owner Port/ PORMS Start Dt/ 29Nov2001

Role Type/ Subject to Marine Inspection Activity Type/ Vessel Inspection

Activity Subtypes/ HULL EXAM

Status/ Closed - Agency Action Complete Date Status Last Changed/ 02Jan2002

Notes (Truncated)/ COMPLETED CREDIT DRYDOCK EXAM. ISSUED ONE REQUIREMENT. NO OTHER REQUIREMENTS ARE OUTSTANDING FROM PREVIOUS INSPECTIONS.

03DEC01 Attended vessel in company of vessel owner Mr. Mick Buell

6. Activity #/ 30841 Orig Port/ PORMS Owner Port/ G-MRI Start Dt/ 01Jul1999

Role Type/ Involved in a Marine Casualty Activity Type/ Incident Investigation

Status/ Closed - Agency Action Complete Date Status Last Changed/ 04Jun2002

Notes (Truncated)/

7. Activity #/ 58518 Orig Port/ PORMS Owner Port/ G-MRI Start Dt/ 10Aug1997

Role Type/ Involved in a Marine Casualty Activity Type/ Incident Investigation

Status/ Closed - Agency Action Complete Date Status Last Changed/ 04Jun2002

Notes (Truncated)/

8. Activity #/ 103217 Orig Port/ PORMS Owner Port/ G-MRI Start Dt/ 25Sep1993

Role Type/ Involved in a Marine Casualty Activity Type/ Incident Investigation

Status/ Closed - Agency Action Complete Date Status Last Changed/ 04Jun2002

Notes (Truncated)/

---Hazardous Cargo Authority---

Vessel is NOT Authorized to carry Hazardous Cargo

---Special Notes---

1. Activity #/ 1376512 Last Revised/ 13Mar2001

Unit/ PORMS

Description/ THIS VESSEL MEETS ONE COMPARTMENT SUBDIVISION STANDARD IN ACCORDANCE WITH 46 CFR 179.220

2. Activity #/ 1424731 Last Revised/ 17Mar1999

Unit/ PORMS

Description/ VERIFIED VOLUME OF ENGINE SPACE FOR INSTALLATION OF FIXED FIRE FIGHTING SYSTEM. SPACE IS 400 CUBIC FEET.

3. Activity #/ 1268292 Last Revised/ 25Mar1992

Unit/ PORMS

Description/ REQUIREMENT FOR E/R VENTILATION IAW 46 CFR 182.20-45 WAIVED BY CID.

---Casualty Summary---

Since/ 14Jun1998

1. Activity #/ 30841

Port/ PORMS

Start Date/ 01Jul1999

Location/

END